



Service Bulletin

PRELIMINARY INFORMATION

Subject: Service Power Steering Message On DIC C056D Stored

Models: 2015 Chevrolet Colorado
2015 GMC Canyon

This PI was superseded to update Condition and Recommendation sections. Please discard PIT5437B

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some Customers may comment of a Service Power Steering message on the DIC. Code C056D may be stored.

Recommendation/Instructions

Check the PSCM for codes.

If code C056D is found, reprogram the PSCM with the latest calibrations.

Important: This information does NOT apply to the 2016 model year.

For any other concerns, perform published diagnostics.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2810625	Power Steering Control Module Reprogramming with SPS	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION