



Service Bulletin

PRELIMINARY INFORMATION

Subject: Coolant Leak at Surge Tank or Radiator Surge Tank Cap Leak

Models: 2015-2016 Chevrolet Silverado 2500/3500
2015-2016 GMC Sierra 2500/3500
With Duramax 6.6L Turbo Diesel Engine (RPO LML)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may comment that there is coolant leaking from the coolant surge tank area of the vehicle. This leak may be around the fill cap or hose areas.

Recommendation/Instructions

If the leak is found to be coming from the Surge Tank, replace the Radiator Surge Tank and Cap together.

Parts Information

Part Number	Description	Quantity
23106015	Surge Tank	1
13502509	Surge Tank Cap	1

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
4031280	Radiator Surge Tank Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION