

Service Bulletin: Seat Cowl Detachment



Notice Information

Posted Date: 6/6/2016 2:51:00 PM
Posted To: Dealer Principal, Service / Technical, Workshop Manager, Service Reception
Subject: Service/Technical

TOL NOTICE (US&CAN) – June 6, 2016

Service Bulletin: Seat Cowl Detachment

Triumph has released a service bulletin regarding the possible detachment of the factory seat cowl on certain Triumph Street Triple Rx models. Internal investigations have identified a need to replace the rubber bump stops on the underside of the rear

seat cowl. Dealers are requested to remove the original rubber bump stops and replace with the rubber damper and the three rubber bump stops supplied in the parts kit (T2307283).

Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next visit to the dealership.

SERVICE BULLETIN: SEAT COWL DETACHMENT		
Bulletin Number	Models Affected	VIN Range
535	Street Triple Rx	From 681920 to 761793

Consult **Triumph Online (TOL) / Service Bulletin Page** (Bulletin # 535) or the attached **SB535** PDF for complete instructions. Please ensure that all relevant staff are up to date on these service instructions.

Reminder: Use the “**VIN Enquiry**” function within TOL (found under the **Service/Technical** drop down menu) to search for any outstanding bulletins or recalls whenever a new motorcycle arrives or a Triumph owner visits your dealership.

For more information, please contact Triumph 24/7 Customer Support at 888.284.6288.

Triumph Motorcycles (America) Ltd, 100 Hartsfield Centre Parkway, Suite 200, Atlanta Georgia, 30354, UNITED STATES
Tel: 001 6788 542010, Fax: 001 6788 542025

