



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Antenna Missing During PDI

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Trax	2016	2017	All	All	All	All

Involved Region or Country	North America
Additional RPO/s:	N/A
Condition	Dealers are unable to locate antenna during PDI
Cause	PDI does not show location of the antenna

### Correction

Antenna is located in the LH trim pocket in the trunk.



<b>Version</b>	1
<b>Modified</b>	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION