

Aftermarket Radar Detectors May Interfere with GPS Antenna

AFFECTED VEHICLES

2013–17 Accord, 2013–15 Crosstour, and 2013--16 Odyssey with navigation system

Something to keep in mind: Aftermarket radar detectors may interfere with the GPS antenna mounted behind the instrument panel. A common issue that's been reported from this interference is the vehicle position (VP) icon isn't in the right spot on the navigation screen.

If you get a vehicle in for this issue, try moving the radar detector away from the GPS antenna and retest. If that fixes this issue, be sure to let the service advisor know so he or she can inform your customer. But if it doesn't, then continue with normal system troubleshooting.