



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Blank Radio Display

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro, Malibu, Volt	2016	2017	All	All	All	All

Involved Region or Country	North America
Additional RPO/s:	IO5 IO6
Condition	Blank Radio Display
Cause	Undetermined at this time.

### Correction

Some customers may comment that the radio will have audio and steering wheel controls will work, but the display is inoperative or blank.

US dealers within 100 miles of Warren Michigan please contact General Motors Technical Assistance center before performing any diagnostics or making any repair attempts.

If your dealer is not within 100 miles of Warren Michigan please perform normal diagnostics.

Version	1
Modified	

### Additional SI Keywords

IO5 IO6

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION