

[Next Unread Message](#)

**View Message**

<b>Sent on</b>	02	19	2016	<b>Expires on</b>	03	03	2016
<b>From</b>	Parts and Service Division						
<b>Subject</b>	Request for Parts: 2014-2016 RDX Leak from Fuel Pump Connection						

**PRIORITY/ACTION REQUIRED**

To: All Acura Service Managers/Consultants  
From: Technical Research & Support Group  
RE: Request for Parts: 2014-2016 RDX Leak from Fuel Pump Connection

This message is solely directed to Acura dealership personnel; please handle accordingly.  
Print this i/V message and provide a copy to the Shop Foreman and all Service Consultants.

**Background**

American Honda (AHM) is investigating certain 2014-2016 RDXs with evidence of fuel leak from the fuel tank to the fuel pump connection. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirements:

1. Must confirm fuel leak from the fuel tank to the fuel pump connection.
2. No previous repair relating to the fuel tank or the fuel pump.

**Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.