



Service Bulletin

PRELIMINARY INFORMATION

Subject: Spark Knock Ping Noise Under Light Acceleration SES Lamp May Be On With DTC P0326 Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2015	2016	SOP	Current	3.6 LFX	All
GMC	Canyon	2015	2016	SOP	Current	3.6 LFX	All

Involved Region or Country	North America and
Additional RPO/s:	3.6 LFX
Condition	Spark Knock Ping Noise under light Acceleration SES lamp may be on with DTC P0326 set
Cause	Some customers may comment that there is a knock or ping type noise under light acceleration. This condition may be more noticeable uphill or while under load. DTC P0326 may be stored in history as well.

Correction

This condition is currently under investigation.

Service Procedure

Road test vehicle to duplicate the condition.

If condition can be duplicated capture a session file with GDS 2 and call technical assistance to open case and upload file.

Clear any DTC's that may be set and release vehicle back to customer.

The use of premium fuel may temporarily correct condition.

Warranty Information

Labor Operation	Description	Labor Time
4081298*	Capture a Session File and Contact Technical Assistance	0.3 hr.
	* This is a unique labor operation for bulletin use only.	

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION