



Service Bulletin

PRELIMINARY INFORMATION

Subject:

Attention:

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade	2015	2017	SOP	END	L86	All
Cadillac	CTS-V	2016	2017	SOP	END	Lt4	All
Chevrolet	Camaro	2016	2017	SOP	END	LT1	All
Chevrolet	Corvette	2017	2017	SOP	END	LT1, LT4	ALL
Chevrolet	Silverado	2014	2017	SOP	END	L83, L86, LV3	ALL
Chevrolet	Suburban	2015	2017	SOP	END	L83, L86	All
Chevrolet	Tahoe	2015	2017	SOP	END	L83, L86	ALL
GMC	Sierra	2014	2017	SOP	END	L83, L86, LV3	ALL
GMC	Yukon	2015	2017	SOP	END	L83, L86	ALL

Involved Region or Country	North America and
Additional RPO/s:	N/A
Condition	A vehicle may have a concern of the SES lamp with a P0106 and P0506.
Cause	This maybe caused by a broken valve spring

Correction

Replace the broken valve spring if the valve did not drop and cause block damage

Service Procedure;

Remove the valve cover and inspect for a broken valve spring.

If a broken valve spring is found inspect the intake manifold for a collapsed runner.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION