



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** (Hybrid) 2-Mode GM TAC Part Restriction for EBCM & BPMV has ended

**Models:** 2009-2013 Cadillac Escalade  
2008-2013 Chevrolet Tahoe and GMC Yukon Hybrid  
2009-2013 Chevrolet Silverado and GMC Sierra Hybrid  
All with Two-Mode Hybrid System (RPO HP2)

*This PI was superseded to End the part restriction. Please discard PIT4383P.*

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

The part restriction has ended for the EBCM (25909777, 20946763) and the BPMV (25914986, 25922981) on 9/22/2016. Thank you for all your help in collecting the data to help improve these parts.

### Recommendation/Instructions

These part number can now be ordered directly through your parts department without TAC authorization.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

### Additional SI Keywords

C0035 C0040 C0045 C0050 C0055 C0110 C0131 C0161 C0186 C0196 C0201 C0242 C0245 C0252 C0253 C0256 C0299 C0455 C0550 C0561 C0569 C0710 C0774 C1100 C1101

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION