

Engine Rattles for 1 to 3 Seconds at Startup

AFFECTED VEHICLES

2015–16 Fit

Does the engine rattle at startup for about **1 to 3 seconds**? What's happening is the lock pin inside the VTC actuator isn't holding the actuator properly. This lets the vane turn within the housing, causing a short rattle at startup.

At this time, we have countermeasured parts in stock, so go ahead and replace the VTC actuator. A service bulletin with troubleshooting and repair info will be available very soon.