

TECHNICAL BULLETIN

LTB00932NAS1

14 APR 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 501-05

Sun Visor Vanity Mirror - Lower-Level Service Repair

AFFECTED VEHICLE RANGE:

Range Rover Evoque (LV)

Model Year: 2012 Onwards
VIN: 000447 Onwards
Assembly Plant: Halewood

MARKETS:

NAS

CONDITION SUMMARY:

Situation: The sun visor vanity mirror, vanity mirror door, and/ or vanity mirror light may fail.

Cause: This may be caused by failures of individual components.

Action: Should a customer express any of these concerns, follow the Service Instruction outlined below which includes the details of certain parts previously not available for ordering.

PARTS:

| | | |
|----------|---|-------------|
| LR075956 | Kit - Sun visor Vanity pack (No label) NAS - Cirrus | Quantity: 2 |
| LR075957 | Kit - Sun visor Vanity pack (No label) NAS - Ivory | Quantity: 2 |
| LR075958 | Kit - Sun visor Vanity pack (No label) NAS - Ebony | Quantity: 2 |

TOOLS:

Refer to the Service Instruction/Workshop Manual for any required special tools.

WARRANTY:

NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.


| DESCRIPTION | SRO | TIME (HOURS) | CONDITION CODE | CAUSAL PART |
|-----------------------|-----------------|--------------|----------------|-------------|
| Vanity mirror - Renew | 76.11.37 | 0.1 | 42 | LR054564 |

NOTE: Normal Warranty procedures apply.


SERVICE INSTRUCTION:


- NOTE: right-hand sun visor shown; left-hand sun visor similar.**

Using a suitable trim tool, remove the sun visor vanity pack.



E190303

2.  **NOTE: right-hand sun visor shown; left-hand sun visor similar.**
Install the new sun visor vanity pack until a 'click' is heard.



E190326