

<b>Reference</b>	SSM72736
<b>Models</b>	Discovery Sport / L550 LR4 / L319 Range Rover / L405 Range Rover Evoque / L538 Range Rover Sport / L494
<b>Title</b>	GEN 2.1 16MY Touch Screen Display Screen Saver Not Holding Setting
<b>Category</b>	Electrical
<b>Last modified</b>	15-Apr-2016 00:00:00
<b>Symptom</b>	207000 Entertainment Systems
<b>Content</b>	<p><strong>Issue:</strong> A customer may report a concern that after setting a screensaver on the infotainment system touch screen display, at the next ignition cycle the screensaver has returned to a blank screen (the screensaver will not save). This is likely to occur in vehicles with either a low-level or mid-level infotainment system that is NOT branded as Meridian on 2016 model year vehicles onwards.</p> <p><strong>Cause:</strong> Software error in the touch screen.</p> <p><strong>Action:</strong> There is no action to be taken currently. Do not replace any components, new software will be published at the earliest opportunity and a technical communication released as appropriate.</p>