



Volkswagen



2016 Golf / GTI / Golf R / SportWagen

Engine	Part	Part Number	Quantity
1.8L Turbo: CXBA, CXBB	Oil Filter	06L115562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	5.5L (5.7qt)
	Drain Plug W/Gasket	06L103801	1
	Air Filter	5QM129620	1

Engine	Part	Part Number	Quantity
2.0L Turbo Diesel: DEJA	Oil Filter	03N115562	1
	VW 507 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	5.5L (5.8qt)
	Drain Plug W/Gasket	N 90813202	1
	Air Filter	5Q0129620B	1
	Fuel Filter (20K Only)	5Q0127177C	1

Engine	Part	Part Number	Quantity
2.0L Turbo GTI: CXCA, CXCB	Oil Filter	06K115562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	5.7L (6.0qt)
	Drain Plug W/Gasket	06L103801	1
	Air Filter	5QM129620	1

Engine	Part	Part Number	Quantity
2.0L Turbo (Golf R): CYFB	Oil Filter	06L115562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	5.7L (6.0qt)
	Drain Plug W/Gasket	06L103801	1
	Air Filter	5Q0129620B	1



Volkswagen



2016 Golf / GTI / Golf R / SportWagen

Miscellaneous	Part	Part Number	Quantity
<i>Miscellaneous</i>	Pollen Filter (20K Only)	5Q0819644A	1
	Pollen Filter (20K Only) Auto	5Q0819653	1
	Front Set Wipers	5G1998002	1
	Rear Wiper Blade (Golf)*	5GM955427(A)	1
	Rear Wiper Blade (GTI)	5G6955427	1
	Rear Wiper Blade (Golf R)	5G6955427A	1
	Battery (Amp. Req. Vary)	000915105*	1
	Battery (Amp. Req. Vary)	000915105*	1
	Battery (Amp. Req. Vary)	000915105*	1

*VIN Required

Resetting the service reminder display

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the service reminder can be reset as follows:

- Switch off the ignition.
- Press and hold the **0.0** button in the instrument cluster
- Switch on the ignition.
- Release the **0.0** button.
- If one of the following messages appears in the display:

Reset oil service?

Do you really want to reset inspection?

- Confirm the request by pressing the **0.0** button in the instrument cluster. A confirmation message appears in the display when the service reminder has been reset.

i Do **not** reset the service reminder between service intervals; otherwise, incorrect information will be displayed.

i The service reminder disappears after a few seconds when the engine is running or after the **OK/RESET** button on the windshield wiper lever or the **OK** button on the multi-function steering wheel has been pushed.

For current fluid capacity charts, they can be found on ServiceNet under the Maintenance tab.