



Tech Tips

TT 27-16-01

Date: August 5, 2016

2016 Touareg – Radar Sensor Fault Code C110300 Adaptive Cruise Control Sensor Misadjusted

Perform a visual inspection of the bracket, clips and under carriage for impact damage. If damage is found, repair without replacing the radar sensor. If you still cannot calibrate, then additional diagnoses is necessary and if no other cause is identified, replace the radar sensor. Please review the damage examples below.

