

SSM  
46096

Some 2015-2016 Edge vehicles may exhibit a roof opening panel that is slow to close, stops, or bounces back while closing. Refer to the revised WSM, Section 501-17 for updated cleaning procedure and diagnostics.