

SSM
46101

Some 2017 Continental vehicles may exhibit a luggage compartment lid under flush to rear quarter panel condition by up to 2.7 millimeters. This is considered normal to allow for proper alignment of the rear tail lamp assemblies. No adjustment is required.