

Technical Journal

TITLE:

Air vents, blisters/bubbles

REF NO: TJ 19967	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada			
3 US 7	PARTNER: '510 Volvo Car USA	ISSUE DATE: 2016-05-26	STATUS DATE: 2016-06-03		
FUNC GROUP: 8819	FUNC DESC: Miscellaneous	Page	1 of 3		

"Right first time in Time"

Attachment

File Name	File Size		
Air freshener1.jpg	0.0159 MB		
Damaged surface.jpg	0.2635 MB		

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
124							2007-2016		-	0-0
134							2011-9999		-	0-0
135							2008-2010		-	0-0
136							2008-2016		-	0-0
137							2016-9999		-	0-0
138							2016-9999		-	0-0
155							2015-9999		-	0-0
156							2009-9999		-	0-0
157							2016-9999		-	0-0
184							1999-2006		-	0-0
234							2017-9999		-	0-0
256							2016-9999		-	0-0
275							2003-2014		-	0-0
285							2001-2008		-	0-0
295							2001-2007		-	0-0
384							2001-2009		-	0-0

Technical Journal 19967



Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
533							2007-2013		-	0-0
542							2006-2013		-	0-0
544							2004-2012		-	0-0
545							2004-2012		-	0-0

CSC Customer Symptom Codes

Code	Description
N2	Instrument panel/dashboard/Blistered/bubbled/peeled

VST Operation Number

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

DESCRIPTION:

* Vehicle types added.

Blisters/bubbles may appear on the air vent surfaces (see picture "Damaged surface. jpg"), follow instructions under Service.

SERVICE:

The blistering of the material is often caused by an air freshener applied directly to the air vents, see picture ("Air freshener1.jpg").

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8819.

To view TJ attachment continue to next page. This TJ has two attachments.

Page 2 of 3 2016-06-03

^{*} Do not attach any sort of air freshener directly on air vents.



Technical Journal 19967





2016-06-03 Page 3 of 3