



Technical Journal

TITLE:

Deco panel front doors, difficult to mount

REF NO:
TJ 31611

ISSUING DEPARTMENT:
Technical Service

CAR MARKET:
United States and Canada

PARTNER:
3 US 7510 Volvo Car USA

ISSUE DATE:
2016-06-15

STATUS DATE:
2016-06-22

FUNC GROUP:
8511

FUNC DESC:
Door upholstery

Page 1 of 3

“Right first time in Time”

Attachment

File Name	File Size
TJ 31611.pdf	0.4652 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256							2016-9999		0000561-0999999	201505-999952

CSC Customer Symptom Codes

Code	Description
L4	Door trim panels/panels/Loose, poor fit, warped, wrinkled

VST Operation Number

DTC Diagnostic Trouble Codes

Text

DESCRIPTION:

If a front door deco panel is replaced, it may be hard to mount the new one on the door panel.

**SERVICE:**

If the steel clips on the new deco panel are black, remove the steel clip pointed out in picture "TJ31611.pdf". It will sit tight with the remaining clips. The hole will be adjusted in production to align better with the clip. (The metal colored, old type of clips has less precision and therefore fits in the hole.)

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8511.

To view TJ attachment continue to next page. This TJ has one attachment.

