

Technical Service Bulletin Number

TSB160118

**Technical Service Bulletin****Subject**

New Exhaust Manifold

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISG12 CM2880 G107
- ISG12 CM2880 G109

Description of Change

This document informs the field of a new exhaust manifold part number. The new exhaust manifold has been redesigned and is thicker to make the exhaust manifold more robust.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Exhaust Manifold	3696187	No	No	3693170

Part Identification

©Cummins Inc



Table 1, Existing Exhaust Manifold.

©Cummins Inc.




Table 2, New Exhaust Manifold.

Service Instructions

New exhaust manifold part number **must** be used if replacing exhaust manifold on an ISG12 CM2880 G107 or ISG12 CM2880 G109.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information		
ESN First	Build Date ¹	Plant
89373919	24 May 2015	Beijing Foton Cummins® Engine Company (BFCEC)
¹ Engine build date can be found on the engine data plate.		

Document History

Date	Details
2016-10-31	Module Created

Last Modified: 01-Nov-2016

Copyright © 2000-2010 Cummins Inc. All rights reserved.