

<b>Reference</b>	SSM73022
<b>Models</b>	F-PACE / X761
<b>Title</b>	X761 - Rear driveshaft output seal leak
<b>Category</b>	Driveline
<b>Last modified</b>	19-Dec-2016 00:00:00
<b>Symptom</b>	510000 Fluid Concerns

**Content**Issue:

Customer may report an oil leak from the underside rear of the vehicle.

Cause:

A concern has been identified on a recently manufactured vehicle where an incorrect driveshaft was fitted resulting in an oil leak from the rear drive unit (RDU). The driveshaft assemblies are sequenced to vehicles during manufacturing process and are model specific. Due to a potential labelling error from the supplier of the driveshaft an incorrectly fitted driveshaft has been identified on a vehicle which will result in an oil leak from the rear drive unit (RDU).

Action:

If an oil leak from the RDU is identified from the driveshaft output shaft please submit an EPQR including photos of the oil leak and the labels on the driveshaft.

**PLEASE NOTE:- This SSM is specific to VIN ranges HA054443 to HA054523 only.**

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.