

Reference	SSM73035
Models	F-TYPE / X152 XE / X760 XF / X260 XJ / X351
Title	ABS Modulator replacement`s - F Type, XJ, XF & XE - 16 MY onwards
Category	Chassis
Last modified	03-Nov-2016 00:00:00
Symptom	301000 Service Brake System

Content Issue: Warranty claims are being submitted for ABS modulator replacement, when the DTC present on the vehicle indicates a specific diagnostic path to be taken, and not resulting in a requirement for replacement.

Cause: Topix Diagnostic procedure not being followed correctly.

Action: Only replace ABS modulator`s when a DTC specifically tells you to, after you have followed the diagnosis route as indicated under DTC – Anti Lock Brake System – section 100 – 00 – General information – Description and operation in Topix.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.