ATTENTION:

GENERAL MANAGER PARTS MANAGER CLAIMS PERSONNEL SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the hoxes provided, right.



SUBARU QUALITY DRIVEN® SERVICE

NUMBER: 09-64-16

DATE: 12/16/16

SERVICE INFORMATION BULLETIN

APPLICABILITY: 2015-17MY WRX and WRX STI

SUBJECT: Sub-Level Sensor Flange Nut Cap Shape Change

2014-2017MY Forester 2012-2016MY Impreza 2013-2017MY Crosstrek

INTRODUCTION:

This Service Information bulletin announces a change to the shape of the rubber cap used on the flange nuts securing the sub-level sending unit to the fuel tank. In addition, two of the caps are now used in production instead of only one. This change was made to enhance productivity during vehicle assembly.

PRODUCTION CHANGE INFORMATION:

The new caps were incorporated into production per the table below:

Vehicle / Model	Starting VIN
WRX / WRX STI	H*813328
Forester	H*437667
Impreza	4 Door- G*021684
	5 Door- G*326025
Crosstrek	G*326025

PART INFORMATION:

The part number for the new style cap is 42031SG000.

SERVICE PROCEDURE / INFORMATION:

The illustrations below show the shape change, location and quantity of the caps used.


Continued...


CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS **ISO 14001 COMPLIANT**

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.





NOTES:

- On vehicles produced after July, 2016, a second cap was added in the location shown above.
- Production of the old style cap has been discontinued. Use the new style cap whenever replacement is required.
- Both the new and old style caps can be reused. They are NOT one-time use items.

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.