



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Headlamps Inoperative After Switching To Snow Plow Lights (GM Upfitter 116)

**Models:** 2014 Chevrolet Silverado 1500  
2015-2017 Chevrolet Silverado  
2014 GMC Sierra 1500  
2015-2017 GMC Sierra

*This PI was superseded to add the 2016/2017 models. Please discard PIT5412.*

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

Some owners with snow plow equipment may notice when they switch from the factory (vehicle) headlights to the snow plow headlights, the snow plow headlights may be inoperative. When checking for DTC's, the BCM may have set a B2575 and/or B2699.

### Recommendation/Instructions

Please reference the latest version of GM Upfitter Integration Bulletin 116 for additional information on these circuits. It can be found at <http://www.gmupfitter.com/>, under the "Technical Bulletin" Tab and then "Show all bulletins."

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION