



Service Bulletin

PRELIMINARY INFORMATION

Subject: Installation Of Electrical Aftermarket Accessories (Battery Ignition And Ground Connections)

Models: 2015-2017 Chevrolet Silverado
2014 Chevrolet Silverado 1500
2015-2017 GMC Sierra
2014 GMC Sierra 1500

This PI was superseded to add the 2016/2017 models. Please discard PIT5326.

Condition/Concern

Upfitters/owners may question where they can install their aftermarket electrical accessories.

Provisions have been provided for the installation of electrical accessories without splicing or cutting into the factory wiring harness. Please reference the latest version of GM Upfitter Integration Bulletin 115 for this information. It can be found at <http://www.gmupfitter.com/>, under the "Technical Bulletin" Tab and then "Show all bulletins."

Important: It is very important that electrical accessories be installed properly and not spliced or cut into the factory wiring harness.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION