



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:**

**Attention:**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2016	2016	All	All	2.8 LWN	N/A
GMC	Canyon	2016	2016	All	All	2.8 LWN	N/A

<b>Involved Region or Country</b>	North America
<b>Additional RPO/s:</b>	2.8 LWN
<b>Condition</b>	A dealer may encounter a customer concern of a Check Engine Light on.
<b>Cause</b>	The dealer may find a DTC P2A00 set active or in history.

### Correction

Complete the current SI diagnostic for any trouble codes or symptoms found.

Be sure to check for a leaking or restricted intake system/charge air hoses, leaking exhaust system/turbo charger and for contaminated or low quality fuel.

If after performing normal SI diagnostics and another root cause is not found, GM Engineering is aware of this concern and is working on a correction.

This Preliminary Information will be updated when further information is available.

<b>Version</b>	1
<b>Modified</b>	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION