



Service Bulletin

PRELIMINARY INFORMATION

Subject: P3400 setting with 8 speed only

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2016	2017	SOP	END	6.2L, LT1	8 Speed
Chevrolet	Corvette	2015	2017	SOP	END	6.2L, LT1	8 Speed

Involved Region or Country	North America
Additional RPO/s:	N/A
Condition	The vehicles listed in the PI may have a concern of a DTC P3400 setting
Cause	Unknown at this time

Correction

There is not a repair at this time Engineering is working on a fix.

Clear the codes and release the vehicle to the customer.

When information becomes available the information will be released.

Warranty Information

Labor Operation	Description	Labor Time
4081398*	Check ECM for DTC P3400 And Clear Codes	0.2 hr
	* This is a unique labor operation for bulletin use only.	

Version	2
Modified	12/12/2016 Updated to add Models

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION