



Service Bulletin

PRELIMINARY INFORMATION

Subject: Washer Reservoir Leaks

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Sonic	2016	2017	ALL		All	All

Involved Region or Country	North America and
Condition	Customer may notice washer fluid leaking
Cause	The washer solvent filler tube seal may be damaged.

Correction

Replace washer solvent container.

Note: Engineering will be requesting the parts for review to root cause the concern.

Parts Information

Description	Part Number	Qty
Washer Solvent Container	95229337	1

Warranty Information

Labor Operation	Description	Labor Time
2070530*	Windshield Washer Solvent Container Replacement	Use published time

*This is a unique Labor Operation for Bulletin use only.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION