



Service Bulletin

PRELIMINARY INFORMATION

Subject: LT4 Supercharger Belt Tensioner Noise with A light Tip In In AFM

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|-----------|----------|-------------|------|------|------|----------|---------------|
| | | from | to | from | to | | |
| Chevrolet | Corvette | 2015 | 2017 | SOP | 2017 | 6.2L LT4 | ALL |

| | |
|----------------------------|--|
| Involved Region or Country | North America |
| Condition | LT4 |
| Cause | There may be a concern with a rattle or flutter noise from the supercharger tensioner and belt. This occurs in V4 mode with light throttle conditions. Issue sounds like tick noise when in driver seat. This seems to vary between vehicles but replacing the tensioner or a softer belt won't resolve the issue. |

Correction

At this time there is not a fix for this concern engineering is working on a fix at this time.

When the fix is released this PI will be updated with the repair.

Warranty Information

| Labor Operation | Description | Labor Time |
|--|---|------------|
| 4081428* | Inspect Supercharger Belt Tensioner For A Rattle or Flutter Noise | 0.3 |
| *This is a unique Labor Operation for Bulletin use only. | | |

| | |
|----------|---|
| Version | 1 |
| Modified | |

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION