



# Service Bulletin


## TECHNICAL

**Subject:** Sharp Edge on Underside of Trunk Shelf

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	LaCrosse	2015	2016			All	All

<b>Condition</b>	Some customers may comment on a sharp edge on the underside of the trunk shelf.
<b>Cause</b>	This may be caused by the underside trim piece (rear window panel stowage compartment cover) being removed from some vehicles, leaving a sharp edge.
<b>Additional Options</b>	Equipped with RPO U65 or UQS

### Correction



If you encounter a vehicle with the above concern, install the rear window panel stowage compartment cover. Refer to Rear Window Panel Stowage Compartment Cover Replacement in SI for installation instructions.

### Parts Information

Description	Part Number	RPO
COVER ASM-R/WDO PNL STOW COMPT	90921263	UQS
COVER ASM-R/WDO PNL STOW COMPT	90921264	U65

### Warranty Information

Labor Operation	Description	Labor Time
1080328*	Rear Window Panel Stowage Compartment Cover Installation Only	0.5 hr
*This is a unique Labor Operation for Bulletin use only.		

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that

your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION