




# Service Bulletin

## TECHNICAL

**Subject:** Instrument Panel Upper Trim Pad Discoloration and/or Shiny Spot

**Attention:** This Bulletin also applies to any of the models that may be Export vehicles.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Express	2016	2016	SOP	August 25, 2015	All	All
GMC	Savana	2016	2016	SOP	August 25, 2015	All	All

<b>Condition</b>	 <p>Some customers may comment on a shiny spot and/or a white discoloration on the instrument panel upper trim pad directly in front of the instrument panel cluster.</p>
<b>Cause</b>	This may be caused by a tooling change within the production of the part.

### Correction

If you encounter a vehicle with the above concern, replace the trim pad. Refer to Instrument Panel Upper Trim Pad Replacement in SI.

### Parts Information

Description	Part Number	Color
PANEL ASM-I/P UPR TR	25861847	Neutral
PANEL ASM-I/P UPR TR	25861848	Pewter

## Warranty Information

Labor Operation	Description	Labor Time
1080318*	Instrument Panel Upper Trim Pad Replacement Due To Discoloration	0.7 hr

\*This is a unique Labor Operation for Bulletin use only.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION