

Bulletin No.: PIE0358

Date: Mar-2016

Service Bulletin

PRELIMINARY INFORMATION

Subject: Engineering Information – Accessory Wheel Flare Warping or Accessory Wheel Flare Tape Separating

Models: 2015-2016 Chevrolet Colorado

2015-2016 GMC Canyon

Equipped with Accessory Wheel Flares (RPO-SF5)

Attention: Proceed with this EI ONLY if the customer has commented about this concern AND the PIE number is

listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard the PI and proceed with diagnostics found in published service information. THIS IS NOT A RECALL — refer to the latest version

of Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins.

Condition

Important: If the customer did not bring their vehicle in for this concern, DO NOT proceed with this EI.

Some customers may comment that the wheel tape is separating from the part or the vehicle, or that the wheel flare is warped.

Cause

GM Engineering is attempting to determine the root cause of the above condition. Engineering has a need to gather information on vehicles PRIOR to repair tha may exhibit this condition. As a result, this information will be used to "root cause" the customer's concern and develop/validate a field fix.

Instructions

If you encounter a vehicle with the above concern, complete the following prior to attempting repairs or removing any parts:

1. Take pictures of the wheels flare areas of separation.

Note: Pictures should be sent using the Field Reporting Process. Submit a report as outlined in the latest version of Corporate Bulletin Number 02-00-89-002 (U.S. Dealers) or 10-00-89-006 (Canada Dealers). The report must include the PIE number for warranty claim payment.

- 2. Note if the tape is separating from the wheel flare or the body of the vehicle.
- 3. Note if the wheel flares are correctly installed over the stone guard on both front and rear of the vehicle.
- 4. Contact one of the engineers listed below.

Contact Information

Engineer Name	Phone Number
Jason Tjernlund	586-859-1530
Caitlin McCarthy	586-552-9934

Please include the following information if leaving a message:

Technician name

- Dealer name and phone number
- Complete VIN and repair order (R.O) number

On the repair order, document the date and time the call was placed (even if the engineer was not reached).

If engineering is unable to return the call within one hour, proceed with diagnosis and repair based on information found in SI.

Warranty Information

If engineer was contacted or required information was provided, use:

Labor Operation	Description	Labor Time
0580188*	Engineering Information — Wheel Flare Warping or Wheel Flare Tape Separating	0.4 hr
*This is a unique Labor Operation for Bulletin use only. It will not be published in the Labor Time Guide.		

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safety. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

