



Service Bulletin

TECHNICAL

Subject: Diagnostic Tip for No Start and Malfunction Indicator Lamp Illuminated with DTC P0C78

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Spark EV	2014	2016				

Condition	<p>Some customers may comment on the following conditions:</p> <ul style="list-style-type: none"> No Start condition. Malfunction Indicator Lamp (MIL) Illuminated. <p>A technician may notice that DTC P0C78 is set.</p>
Cause	This condition may be caused by a faulty Coolant Heater Control Module (K10).

Correction

For vehicles that exhibit a No Start along with DTC P0C78, install a new Coolant Heater Control Module (K10).

Service Procedure

Refer to the repair instructions in the HVAC section in SI.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4414090	Heater Coolant Heater Replacement	Use Published Labor Operation Time

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that

your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION