



Service Bulletin

PRELIMINARY INFORMATION

Subject: Engineering Information – Loss of Audio, Chimes or Turn Signal Click/Clack with DTC U0180 or B1325 sym03

Models: 2013-2016 Cadillac ATS
2014-2016 Cadillac CTS (VIN A)
Equipped with Premium Audio Amplifier (RPOs UQA or UQS)

This PI has been revised to end the need for information from the field. Please discard PIE0348.

If you encounter a vehicle with this concern, please refer to SI diagnostics.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION