



Service Bulletin

TECHNICAL

Subject: Diagnostic Tip for IPC B1370 History Code Set

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|--------|---------|-------------|------|------|----|---------|---------------|
| | | from | to | from | to | | |
| Buick | Cascada | 2016 | 2016 | | | | |

| | |
|------------------|--|
| Condition | During a normal diagnostic check, the technician may find B1370 stored in history on the IP Cluster with no apparent IPC concerns from the customer. |
| Cause | The B1370 code will set in history any time a remote start is initiated as a course of normal operation. |

Correction

If there are no IPC concerns from the customer, disregard and clear history code. If there is an IPC concern and the B1370 code returns as current or history with no remote start events since clear, follow normal SI diagnostics for IPC B1370.

| | |
|-----------------|---|
| Version | 1 |
| Modified | |

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION