



Service Bulletin

PRELIMINARY INFORMATION

Subject: Radio Display Continuously Flashes On and Off After Starting Vehicle

Models: 2016 Buick LaCrosse, Regal
2016 Cadillac ATS, ATS-V, CTS, CTS-V, ELR, Escalade models, XTS
2016 Chevrolet Camaro, Colorado, Corvette, Impala, Malibu, Silverado, Suburban, Tahoe, Volt
2016 GMC Canyon, Sierra, Yukon models
Equipped with RPO code IO5 or IO6

Condition/Concern

Some customers may comment the radio display is continuously flashing on and off every 5 seconds. The backlighting will flash with or without an image on the display. Cycling the key or battery power will not correct the concern.

Recommendation/Instructions

Please replace the Human Machine Interface (HMI) for this concern.

Parts Information

Contact an Electronic Service Center (ESC) for an exchange HMI following current exchange process.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
3421060	Human Machine Interface Control Module Replacement	Use Published Labor Operation Time

Additional SI Keywords

CUE, IntelliLink, MyLink

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION