



Service Bulletin

PRELIMINARY INFORMATION

Subject: 3.6L LF4 Twin Turbo Charged Engine Exchange Program Ending

Models: 2016 Cadillac ATS- V Series
Equipped with a 3.6L Twin Turbo Charged Engine (Vin code Y- RPO Code LF4).

This PI was superseded to update Engine Exchange. Please discard PIP5287.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Recommendation/Instructions

As part of our ongoing quality improvement efforts the 3.6L Twin Turbo Charged Engine (VIN code Y-RPO Code LF4) engine was placed on restriction through the PQC to assist Engineering with productfeedback.

As of 3/2/2016 the restriction on the 3.6L Twin Turbo Charged Engine (VIN code Y- RPO Code LF4)has ended. This engine can now be ordered through the regular GMSPO parts process or PQCprocess for required dealers.

GM Engineering would like to thank all dealers that participated in this parts restriction.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION