



Countries: RUSSIA, AUSTRALIA, BAHAMAS, BOLIVIA, BELIZE, CANADA, CHILE, TAIWAN, COLOMBIA, COSTA RICA, DOMINICAN REPUBLIC, ECUADOR, EL SALVADOR, TRINIDAD AND TOBAGO, UNITED STATES, URUGUAY, VENEZUELA, ARUBA, NICARAGUA, PERU, PUERTO RICO, Curaçao, GUAM, GUATEMALA, GUYANA, HAITI, HONDURAS, JAMAICA, KOREA, SOUTH KOREA, NEW ZEALAND, PANAMA

Document ID: IK1200883

Availability: ISIS, Bus ISIS, Fleet ISIS

Revision: 12

Major System: ENGINES

Created: 2/7/2013

Current Language: English

Last Modified: 1/4/2016

Other Languages: [Español](#)

Author: Caleb Iverson

Viewed: 10239

[Less Info](#)
[Hide Details](#)

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		View My Bookmarks				53	14

Title: Exhaust Manifold Ring Seal Kit Installation

Applies To: EPA 10 MaxxForce® DT, 9, and 10 Engines and EPA 10 MaxxForce® DT, 9, and 10 with HD-OBID Engines

CHANGE LOG

2016/01/04 - Removed MaxxForce 11, 13, and N13 tags.
 2015/11/05 - Updated link for MaxxForce 11, 13, and N13
 2015/06/26 - Updated coding to include New Zealand, Australia, Russia
 2014/11/03 - Edited attribute coding
 2014/09/16 - Author updated for feedback purposes

DESCRIPTION

The purpose of this iKNOW Article is to show that there are TSI letters that show the procedure for removal and installation of the Exhaust Manifold Ring Seal Kit.

See TSI 13-12-21 for information regarding the Removal and Installation of the Exhaust Manifold Ring Seal Kit.

For EPA 10 MaxxForce® DT, 9, and 10 Engines and EPA 10 MaxxForce® DT, 9, and 10 with HD-OBID Engines **Not Equipped with Inner-Stage Cooler (ISC)** Refer to the TSI link below.

<https://evaluate.internationaldelivers.com/service/SVCDOCS/Navistar/tsipdf/131221.pdf>

If the link above does not work, you can also find the TSI on the Service Portal > Publications > Master Service Information > Search TSIs.

See TSI 13-12-23 for information regarding the Removal and Installation of the Exhaust Manifold Ring Seal Kit.

For EPA 10 MaxxForce® DT, 9, and 10 Engines and EPA 10 MaxxForce® DT, 9, and 10 with HD-OBID Engines **Equipped with Inner-Stage Cooler (ISC)** Refer to the TSI link below.

<https://evaluate.internationaldelivers.com/service/SVCDOCS/Navistar/tsipdf/131223.pdf>

If the link above does not work, you can also find the TSI on the Service Portal > Publications > Master Service Information > Search TSIs.

[Hide Details](#)

Feedback Information

Viewed: 10238
 Helpful: 53
 Not Helpful: 14

Staff ID	Client ID	Comments	Created Date
	DY08955		

	You received the following feedback From: dy08955 - David Gabrielle Email Address: gabe396@aol.com Job Classification: SE008, Service Technician Dealer: TRUCK KING INTL IDEALEAS Feedback: I'm installing Kit 7092423C91 on a 2010 Maxx 13. The instruction sheet in the kit states to refer to IK1200883 for the procedure. The two TSI letters listed in this IK1200883 are for a Maxx DT. What happened to the Maxx 13 ?	1/15/2016 12:07:22 PM
--	--	--------------------------

Copyright © 2016 Navistar, Inc.