



# Service Bulletin

## TECHNICAL

**Subject:** Rear Camera Inoperative - Backup Lamps Inoperative - F6 Fuse Open

Brand:	Model:	Model Year:	VIN:		Engine:	Transmission:
			from	to		
Buick	Encore	2015				

<b>Condition</b>	<p>Some customers may comment on the following conditions:</p> <ul style="list-style-type: none"> <li>Rear view camera inoperative.</li> <li>Rear backup lamps are inoperative.</li> </ul> <p>Technicians may notice the F6 fuse was open.</p>
<b>Cause</b>	This condition may be caused by a shorted driver side sunshade lamp circuit.

### Correction

If the F6 fuse is open and the sunshade has been validated to be the cause of the short, the driver side sunshade must be replaced.

### Service Procedure

Refer to *Sunshade Replacement* in SI.

### Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
1040390	Sunshade Replacement	Use Published Labor Operation Time

<b>Version</b>	1
<b>Modified</b>	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that

your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION