



Service Bulletin

TECHNICAL

Subject: Inconsistent or Erratic Sunshade Operation

Attention: This Bulletin also applies to any of the models that may be Export vehicles.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu	2016		SOP	1G1ZE5ST7GF 180333	All	All

Condition	Some customers may comment about erratic or inconsistent sunroof or sunshade operation. The sunshade can close the opening when the glass is open.
Additional Options	VIN Z (4th digit, New Style Malibu) equipped with RPO C3U, SUN, GLASS, SLIDING, ELEC, TRANSPARENT GLASS FIXED

Correction

A revised calibration has been developed to address these concerns. Update the Body Control Module (BCM) using the Service Programming System (SPS).

Service Procedure

Follow programming procedure instructions in *Body Control Module Programming and Setup* in SI.

Warranty Information

Labor Operation	Description	Labor Time
2810215	Body Control Module Reprogramming with SPS	0.5 hr

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION