



Service Bulletin

INFORMATION

Subject: Difficulty Programming Dealer Installed Accessory Remote Start

Attention: This Bulletin also applies to any of the models that may be Israel Export vehicles.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu (VIN Z)	2016					

Condition	A technician may have difficulty with programming the vehicle for remote start when ordered with dealer installed accessory.
Additional Options	RPO S6P

Correction

If the vehicle was ordered with the Accessory Remote Start kit, **there is no programming required**. Only learn the new transmitter (FOBs) to the vehicle and the install is complete. This can be verified by checking the VIN in the Investigate Vehicle History (IVH) system. If the vehicle was built with RPO Code S6P, the vehicle was produced with the correct system software and no call to TCSC is required.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION