



# Service Bulletin

## TECHNICAL

**Subject:** Service Headlamp Leveling System Message, DTC B101E Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Cascada	2016	2016				

<b>Condition</b>	During pre-delivery inspection (PDI), a technician may find service headlamp leveling system message on the driver information center (DIC) with DTC B101E Sym00 code present.
<b>Cause</b>	This condition may be due to the programming for the headlamp module not fully completed at the assembly plant.

### Correction

Run set-up and configuration of headlamp control module and clear codes. If the message on the driver information center (DIC) and/or DTC B101E is present, pursue further diagnostics in SI.

### Service Procedure

Refer to *Headlamp Control Module Programming and Setup* in SI.

### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810475	Headlamp Control Module Reprogramming with SPS	Use Published Labor Operation Time

<b>Version</b>	1
<b>Modified</b>	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION