



Service Bulletin

TECHNICAL

Subject: Service Power Steering System Message on the DIC, Increased Steering Effort, DTC C056D Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2016	2016				
GMC	Canyon						

Condition	<p>Some customers may comment on the following conditions:</p> <ul style="list-style-type: none"> • Service Power Steering message on DIC. • Loss of power steering assist. <p>A technician may find DTC C056D set as an Active or History DTC.</p>
Cause	This condition may be caused by a faulty power steering assist motor.

Correction

If DTC C056D has been set, calibration update of the power steering control module does **not** need to be performed. The power steering assist motor must be replaced.

Service Procedure

Refer to *Power Steering Assist Motor Replacement* in SI.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
7420270	Power Steering Assist Motor Replacement	Use Published Labor Operation Time

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION