

Reference	SSM73079
Models	Range Rover / L405 Range Rover Sport / L494
Title	D7u 16MY Abnormal steering after stop/start event
Category	Chassis
Last modified	02-Dec-2016 00:00:00
Symptom	303000 Steering/Handling

Content

Affects all 16MY D7u vehicles
L494 16MY
L405 16MY

Issue:
Abnormal steering feel after stop/start event.

Cause:
Power Steering Control Module (PSCM) system calibration error.

Action:
Re-flash PSCM ensuring Symptom Driven Diagnostics Tool (SDD) is running - SDD_147.06.001 or later.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.