



**Countries:** CANADA, UNITED STATES **Document ID:** IK1201323  
**Availability:** ISIS **Revision:** 0  
**Major System:** ENGINES **Created:** 2/22/2016  
**Current Language:** English **Last Modified:** 2/23/2016  
**Other Languages:** NONE **Author:** Michael Sokolowski  
**Viewed:** 118

[Less Info](#)

Hide Details

Coding Information

<b>Copy Link</b> 	<b>Copy Relative Link</b> 	<b>Bookmark</b>  <a href="#">View My Bookmarks</a>	<b>Add to Favorites</b> 	<b>Print</b> 	<b>Provide Feedback</b> 	<b>Helpful</b>  4	<b>Not Helpful</b>  0
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	-------------------------	-----------------------------

**Title:** Aftertreatment Fuel Injector Replacement

**Applies To:** ProStar with ISX15

## CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

02/23/2016 - Initial Article Release

## SUBJECT

Cummins® ISX15 Aftertreatment Fuel Injector Replacement

## DESCRIPTION

Model year 2013 and newer international prostar chassis have a clean air cabin filter water drain above the aftertreatment fuel injector which allows rain and wash water to drip or pour onto the aftertreatment fuel injector. over time, the internal components of the aftertreatment fuel injector corrode, rendering the aftertreatment fuel injector inoperable.

Cummins® has issued a TSB with procedures on the replacement and sealing of the aftertreatment injector.

Please refer to the "TSB" tab under the "Service" section on Quickserve Online (QSOL) to determine if this article pertains to your vehicle. See figure 1 below.

The screenshot shows the Cummins Quickserve Online (QSOL) interface. At the top, there are navigation tabs: Manuals, Dataplate, Campaigns, TRPs, Service Bulletins, TSBs, What's New, and Service Tools. Below these are search filters: Maintenance, Fault Code Search, Symptom Search, and Related Information. The main content area is titled "Technical Service Bulletins" and contains a search bar with the text "tsb160008" and a "Search" button. Below the search bar, there is a "Display Technical Service Bulletins" button. The search results are displayed under the heading "TSB Search Results" and show one entry: "Aftertreatment Fuel Injector Replacement on International® Prostar® Chassis". The entry details include "Product Affected ISX15 CM2350 X101 (International® Prostar® Truck Only)" and "Issue Model year 2013 and newer International™ Pro Star chassis have a clean air cabin filter water drain above the aftertreatment fuel injector which allows rain and wash water t". The entry is identified as "tsb160008 | English | 20160203". At the bottom of the search results, it says "Showing 1 to 1 of 1 entries" and includes navigation buttons: First, Previous, 1, Next, Last.

---

## **REPAIR PROCEDURE**

For repair actions refer to the instructions for **TSB160008** located on QuickServe Online.

---

## **WARRANTY INFORMATION**

The information in this document has no effect on Navistar's present warranty coverage or repair practices, nor does it authorize campaign actions. See **TSB160008** on QSOL for further warranty guidelines.

Link to QuickServe Online:

<https://quickserve.cummins.com/qs3/portal/index.html>

 Hide Details

Feedback Information

Viewed: 117

Helpful: 4

Not Helpful: 0

No Feedback Found

---

Copyright © 2016 Navistar, Inc.