

TECHNICAL SERVICE BULLETIN

Group:	0-GENERAL
Bulletin No:	SB-15-048
Issue Date:	4-11-2016
Vendor Ref.:	HMM-151208-J1


DPF SHIELD BRACKET CORROSION

SUBJECT VEHICLES: 12MY-16MY COE (Cab over Engine) Trucks (195, 195h)

Note: This service bulletin is provided as technical information and is not authorization for a warrantable repair.

OVERVIEW:

Subject vehicles may exhibit a broken DPF shield mounting bracket due to corrosion perforation. An enhanced DPF shield bracket made from stainless steel is now available to prevent this condition from recurring.



PARTS:

PART NUMBER	DESCRIPTION	QUANTITY
1754378020	DPF Shield Bracket	2
SZ10508083	Bracket Bolt	6 (As Required)
SZ17808015	Bracket Nut	6 (As Required)
9167180825	Shield Bolt	4 (As Required)



A Toyota Group Company

TECHNICAL SERVICE BULLETIN

Group:	0-GENERAL
Bulletin No:	SB-15-048
Issue Date:	4-11-2016
Vendor Ref.:	HMM-151208-J1

Note: This service bulletin is provided as technical information and is not authorization for a warrantable repair.

CLAIM APPLICATION

** Reimbursable in accordance within the terms and policies of the Hino limited warranties.*

DPF Shield Bracket:

Labor Charge: 0.5 Hours

Warranty Code: 11527

Trouble Code: 60

Operation Code: 11527ARE

Part Number: 17543E0010



A Toyota Group Company