

Technical Service Bulletin

40 Left drive shaft, clattering noises when accelerating

40 16 51 2043423/1 February 23, 2016.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
Q3	2015	All	Not Applicable	
Q3	2016	000001 - 036317	Not Applicable	

Condition

A rattling noise is heard from the left front area of the vehicle when both of the following conditions are present:

- During hard/aggressive acceleration in first or second gear.
- After a cold start, with the noise disappearing after the vehicle reaches operating temperature.

Note:

This bulletin only applies to vehicles matching this condition. Do not perform this bulletin if the complaint does not exactly match the condition.

Technical Background

The noise is caused by the left front driveshaft.

Production Solution

Not applicable.

Service

- 1. Before proceeding, test drive the vehicle to duplicate the noise and to confirm that the noise is coming from the left front driveshaft area.
- 2. Replace the left front driveshaft.

© 2016 Audi of America, Inc.

Page 1 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.				
Service Number:	4041				
Damage Code:	0020				
Labor Operations:	Driveshaft remove+reinstall	4041 1900	90 TU		
Diagnostic Time:	GFF	No allowance	0 TU		
	Road test prior to service procedure	0121 0002	10 TU		
	Road test after service procedure	0121 0004	10 TU		
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)				
Claim Comment:	As per TSB #2043423/1				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
See ETKA	Left front driveshaft	1

Additional Information

All parts and service references provided in this TSB (2043423) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

^{© 2016} Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.