

2/10/2016 MY 13, 14, 15, 16 WD, WK

## GPOP - Issue Review System

**Part Number:** 5LC23DX9A\$, 5LC23HL9A\$, 5LC23LU5A\$, 5LC23HL1A\$, 5LC23LC5A\$,  
5LC33BD3A\$, 5LC33DX9A\$, 5LC38DX9A\$, 5LC39DX9A\$, 5XJ96DX9A\$,  
5XJ95DX9A\$, 5XJ95HL1A\$, 5XJ95LC5A\$, 5XJ95LU5A\$

**Part Description:** Load Floor Handle

---

**Issue Description:** If you are in need of a load floor handle, please just order the handle, it is no longer necessary to replace the load floor assembly for a replacement load floor handle

~

Handle pn's : 6BE97TRMAA, 6BF24TRMAA, 6BF25TRMAA are available for service.~

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

---