



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-294

Date: September, 2016

INFORMATION

Subject: Wave Appearance in Folding Top Cloth Between Number 1 and 2 Bow

This Bulletin replaces PIC5683. Please discard PIC5683.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2011	2012			All	All

Involved Region or Country	North America, Europe, Middle East, Japan, Russia, Chile
Additional Options (RPO)	Equipped with Convertible Top
Condition	Some customers may comment on a wave in the convertible top cloth between the #1 and #2 bows on either side of the vehicle when the top is closed.
Cause	This may be due to an elastic cord pulling on the underside of the cover. This elastic cord is in place to ensure the top fabric folds properly as the top is opened.

Correction



2859706



2859707

These waves are characteristic of the design and considered normal.

Do not attempt to repair this condition. It is characteristic of design and all vehicles will exhibit this wave. Do not attempt to modify or in any way change the operation of the elastic cords.

Changes or modifications to this cord can result in permanent damage to the folding top, which would not be covered under the vehicle's warranty.

Version	1
Modified	

