



# Service Bulletin

File in Section: -

Bulletin No.: 16-NA-297

Date: September, 2016

## INFORMATION

**Subject:** Information on Convertible Roof Rivet Replacement


**This Bulletin replaces PIC5831. Please discard PIC5831.**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2011	2015			All	All

<b>Involved Region or Country</b>	North America and N.A. Export Regions
<b>Additional Options (RPO)</b>	Equipped with Convertible Top
<b>Condition</b>	The Electronic Parts Catalog (EPC) may show multiple different rivet sizes and this could create confusion regarding which rivet is needed for which location.

### Correction

Use the following illustration to help aid in the obtaining of the correct rivet needed for the repair being performed.



### Legend

- (1) Part Number 11546538
- (2) Part Number 11546537

Version	1
Modified	

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION